94-330991/41 H01 BORE-90.06.16
BOREHOLE CONSCLIDATION MUDS "SU 1818459-A1
90.06.16 90SU-4862833 (93.05.30) B21B 29/10
Casing string repair kit - has corrugated tube with outer hard metal spots of height exceeding thickness of sealing outer coating of carpanded tube
C34-150749
Addal. Data: NIKITCHENKO V G, KISELMAN M L, MISHENKO V A

The kit includes a hollow tube which has longitudinal corrugations and is coated on the outside with a scaling material. Spots (4) of metal of hardness exceeding that of the repaired casing are deposited in the longitudinal depressions on the outer surface. Height of the metal spots exceeds thickness of the sealing material coating on the tube after it is expanded.

USE

To repair leaking or damaged casing strings in gas, oil wells, in patching up open holes in hard rock and in the coal mining, during drilling of prospecting and other holes.

(2pp1614DwgNo.1/2)

SU 1818459-A

© 1994 DERWENT PUBLICATIONS LTD.

14 Great Queen Street, London WC2B 5DF

US Office: Derwent Inc., 1313 Dolley Madison Boulevard,

Suite 401 McLean, VA22101, USA

Unauthorised copying of this abstract not permitted

#### ... SU ... 1818459 A1

605 E 21 B 29/10

(FOCHATEM) (CCCP)

# ОПИСАНИЕ ИЗОБРЕТЕНИЯ

К АВТОРСКОМУ СВИДЕТЕЛЬСТВУ

1

(21) 4862853/03

(22) 16.06.90

(46) 30.05.93. Бюл. № 20

(71) Всесоюзный научно-исследовательский и проектный институт по креплению скважин и буровым растворам

(72) В.Г.Никитченко, М.Л.Кисельман. В.А.Мишенко и А.Г.Ярыш

(56) Патент США № 3179168. кл. 166-14. опублик, 1965.

Авторское свидетельство СССР N: 1710694. Kn. E 21 B 29/10, 1989.

(54) ПЛАСТЫРЬ ДЛЯ РЕМОНТА ОБСАДной колонны

2

(57) Сущность изобретения: устройство содержит металлическую продольно-гофрированную трубу с герметизирующим покрытием на наружной поверхности. Во впадинах гофр пластыря на наружной поверхности расположен армирующий материал в виде наплавок из материала с твердостью больше твердости материала ремонтируемой трубы. Высота наплавки имеет высоту, превышающую толщину герметизирующего покрытия после расширения пластыря. 2 ил.

Изобретение относится к нефтегазодобывающей промышленности и может быть использовано для восстановления герметичности скважин при ремонте обсадных колонн.

Целью изобретения является повышение надежности соединения пластыря с обсадной трубой за счет исключения продольного смещения пластыря после его установки.

На фиг. 1 показан пластырь: на фиг. 2 разрез А-А на фиг. 1.

Пластырь состоит из продольно-гофрированной трубы 1. наружная поверхность которой покрыта герметиком 2, во впадинах пластыря 3 выполнены наплавки 4.

Установка пластыря в ремонтируемой скважине осуществляется следующим обра-

Пластырь спускают в скважину и расширяют дорнирующей головкой. При расширении пластыря 1 до сопряжения с обсадной трубой наплавки 4 гранями врезаются в обсадную колонну за счет увеличения твердости по сравнению с твердостью металла колонны. При этом герметик 2. обладая пластичностью, создает контактную прочность пластыря с колонной, а наплавки предотвращают его страгивание при создании избыточных усилий при протегивании дорнирующей головки.


Предложенный пластырь может быть использован для восстановления герметичности обсадных колонн, имеющих повреждения в виде отверстий, трещин, износа стенок, разрывов и других дефектов.


Такой пластырь может найти применение также при установке пластырей в открытом стволе в интервале твердых пород (песчаники и др.), например в угольной промышленности при бурении разведочных и других скважин.

Формула изобретения Пластырь для ремонта обсадной колонны, включающий металлическую продольно-

гофрированную трубу, герметизирующее покрытие и расположенный во впадинах гофр армирующий материал с твердостью, большей твердости материала ремонтируемой колонны, о т л и ч а ю щ и й с я тем, что. 5 с целью повышения надежности соедине-

ния пластыря с обсадной трубой за счет исключения продольного смещения пластыря после его установки, армирующий материал выполнен в виде наплавки высотой, превышающей толщину герметизирующего покрытия после расширения пластыря.





Редактор	Составитель В.Н. Техред М.Морген	
Заказ 1930	Тираж	Подписное
ВНИИПИ Государ	ственного комптета по и	изобретениям и открытиям при I KI (I ССР
	113035 Москва Ж-35	Раушская наб . 4/5
		and the same of th

[see English abstract—separate page]

[state seal]

Union of Soviet Socialist Republics

(19) **SU** 

(11) 1818459 A1

USSR State Patent Office (GOSPATENT USSR)

(51)5 E 21 B 29/10

# SPECIFICATION OF INVENTOR'S CERTIFICATE

(21) 4862853/03

(22) June 16, 1990

(46) May 30, 1993, Bulletin No. 20

(71) All-Union Scientific-Research and Planning Institute of Well Casing and Drilling Muds

(72) V. G. Nikitchenko, M. L. Kisel'man, V. A. Mishenko, and A. G. Yarysh (56) US Patent No. 3179168, cl. 166-14, published 1965.

USSR Inventor's Certificate No. 1710694, cl. E 21 B 29/10, 1989. (57) Essence of invention: The device contains a longitudinally corrugated metal tube with a sealing coat on the exterior surface. In the grooves of the patch corrugations on the exterior surface, a reinforcing material is disposed in the form of weld beads made from material with hardness greater than the hardness of the material in the pipe to

be repaired. The height of the weld bead

(54) PATCH FOR CASING REPAIR

sealing coat after expansion of the patch. 2 drawings.

is greater than the thickness of the

[vertically along right margin]

(19) **SU** 

(11) **1818459 A1** 

The invention relates to the oil and gas production industry and may be used to restore leaktightness in wells when repairing casings.

The aim of the invention is to improve the reliability of joining of the patch to the casing by eliminating longitudinal shifting of the patch after it is set.

Fig. 1 shows the patch; Fig. 2 shows section A-A in Fig. 1.

The patch consists of a longitudinally corrugated tube 1, the exterior surface of which is coated with sealant 2, and weld beads 4 are implemented in the grooves of patch 3.

The patch is placed in the well to be repaired as follows.

The patch is lowered into the well and expanded by a coring head. When patch 1 is expanded until it joins with the casing, weld beads 4 cut facewise into the casing

because they are harder than the metal in the string. In this case, sealant 2, which possesses plasticity, creates the contact strength between the patch and the string, while the weld beads prevent it from shifting when excess stresses are created as the coring head is pulled through.

The proposed patch can be used to repair leaks in casings having damage in the form of holes, cracks, wear on walls, breaks, and other defects.

Such a patch may also be used in setting patches in an open hole in an interval of hard rocks (sandstone, etc.), for example in the coal industry when drilling exploratory and other holes.

Claim

A patch for casing repair, including a longitudinally

corrugated metal tube, a sealing coat, and reinforcing material disposed in the grooves of the corrugations with hardness greater than the hardness of the material in the string to be repaired, *distinguished* by the fact that, with the aim of improving the reliability of joining

4

of the patch to the casing by eliminating longitudinal shifting of the patch after it is set, the reinforcing material is implemented in the form of weld beads of height greater than the thickness of the sealing coat after expansion of the patch.

[see Russian original for figures]

Fig. 2

Fig. 1

Editor	Tech. Editor M. Morgental		Proofreader A. Obruchar
Order 1930	Run	Subscription	edition
		ventions and Dechnology [VI	viscoveries of the State

"Patent" Printing Production Plant, 101 ul. Gagarina, Uzhgorod

#### **AFFIDAVIT OF ACCURACY**

I, Kim Stewart, hereby certify that the following is, to the best of my knowledge and belief, true and accurate translations performed by professional translators of the following patents from Russian to English:

RU2016345 C1 RU2039214 C1 RU2056201 C1 RU2064357 C1 RU2068940 C1 ATLANTA RU2068943 C1 BOSTON RU2079633 C1 BRUSSELS RU2083798 C1 CHICAGO RU2091655 C1 DALLAS RU2095179 C1 DETROIT RU2105128 C1 FRANKFURT RU2108445 C1 HOUSTON RU21444128 C1 LONDON SU1041671 A LOS ANGELES SU1051222 A SU1086118 A MINNEAPOLIS SU1158400 A **NEW YORK** SU1212575 A PARIS SU1250637 A1 PHILADELPHIA SU1295799 A1 SAN DIEGO SU1411434 A1 SAN FRANCISCO SU1430498 A1 SEATTLE SU1432190 A1 WASHINGTON, DC SU 1601330 A1 SU 001627663 A SU 1659621 A1 SU 1663179 A2 SU 1663180 A1 SU 1677225 A1 SU 1677248 A1 SU 1686123 A1 SU 001710694 A SU 001745873 A1 SU 001810482 A1 SU 001818459 A1 350833 SU 607950 SU 612004 620582 641070 853089 832049

WO 95/03476

Page 2 TransPerfect Translations Affidavit Of Accuracy Russian to English Patent Translations

Kim Stewart

TransPerfect Translations, Inc.

3600 One Houston Center

1221 McKinney

Houston, TX 77010

Sworn to before me this 23rd day of January 2002.

Signature, Notary Public

My Control My

OFFICIAL SEAL
MARIA A. SERNA
NOTARY PUBLIC
in and for the State of Texas

Stamp, Notary Public

**Harris County** 

Houston, TX

# This Page is Inserted by IFW Indexing and Scanning Operations and is not part of the Official Record

### **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

BLACK BORDERS

IMAGE CUT OFF AT TOP, BOTTOM OR SIDES

FADED TEXT OR DRAWING

BLURRED OR ILLEGIBLE TEXT OR DRAWING

SKEWED/SLANTED IMAGES

COLOR OR BLACK AND WHITE PHOTOGRAPHS

GRAY SCALE DOCUMENTS

LINES OR MARKS ON ORIGINAL DOCUMENT

REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY

## IMAGES ARE BEST AVAILABLE COPY.

OTHER:

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.